

Marine Notice No. 36 of 2024

Notice to all owners, charters, brokers and users of recreational craft

Product Warning: SUN ODYSSEY

1. Notification of product warning

The Department of Transport has been notified of the potential risk with the recreational craft Sun Odyssey. The manufacturer Jeanneau has published safety information for owners of Jeanneau Sun Odyssey 410, 440 and 490 at the following link: <u>https://www.jeanneau.com/en-us/info-sun-odyssey</u>

A summary is set out below of the notice for the Jeanneau Sun Odyssey 410, 440 and 490 with full details on the attached notice:

2. Description of all three notices

| <u>Name</u> : | Sun Odyssey 410, SPBI-Jeanneau |
|----------------------|---|
| Product Description: | Recreational Craft produced between 2020 to 2022. |
| <u>Risk Type</u> : | Drowning |
| Risk Description: | Due to a gluing problem, the bow thruster flange may detach and generate leaks. The boat may sink, increasing the risk of drowning for users. |
| Country of origin: | Unknown |
| End user action: | Take notice of the warning to consumers of the recall of the product from end users. |
| | |
| Name: | Sun Odyssey 440, SPBI-Jeanneau |
| Product Description: | Recreational Craft |

Risk Type: Drowning

| Risk Description: | Due to a gluing problem, the bow thruster flange may detach and generate leaks. The boat may sink, increasing the risk of drowning for users. |
|-----------------------|---|
| Country of origin: | France |
| End user action: | Take notice of the warning to consumers of the recall of the product from end users. |
| | |
| <u>Name</u> : | Sun Odyssey 490, SPBI-Jeanneau |
| Product Description: | |
| r toduct Description. | Recreational Craft |
| Risk Type: | Recreational Craft Drowning |
| | |
| Risk Type: | Drowning Due to a gluing problem, the bow thruster flange may detach and generate leaks. The boat may sink, increasing the risk |

Owners, charters and brokers are advised to refer to the Jeanneau website containing important safety information for these vessels at the link given above.

Encl: Recall Notices

Irish Maritime Administration, Department of Transport, Leeson Lane, Dublin 2, D02 TR60, Ireland. 24/06/2024

> For any technical assistance in relation to this Marine Notice, please contact: The Marine Survey Office, email: <u>MSO@transport.gov.ie</u>. For general enquiries, please contact the Maritime Safety Policy Division, email: <u>MaritimeSafetyPolicyDivision@transport.gov.ie</u>. Written enquiries concerning Marine Notices should be addressed to: Dept. of Transport, Maritime Safety Policy Division, Leeson Lane, Dublin 2, D02 TR60, Ireland. email: <u>MarineNotices@transport.gov.ie</u> or visit us at: <u>www.gov.ie/transport</u>.



| Notifying country | France |
|---|--|
| Product category | Recreational crafts |
| Туре | Consumer |
| Product | Recreational craft |
| Name | SUN ODYSSEY 410 |
| Brand | SPBI-JEANNEAU |
| Product description | Recreational craft. Production dates: 2020 to 2022. Product sold online. |
| Risk type | Drowning |
| Risk description | Due to a gluing problem, the bow thruster flange may detach and generate a waterway. The boat may sink, increasing the risk of drowning for users. |
| Legal provisions (at EU level) and European standards against which the product was tested and did not comply | The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive. |
| Country of origin | Unknown |
| Measures taken by economic operators | Recall of the product from end users Manufacturer |

Date of entry into force 16/05/2024



| Notifying country | France |
|---|--|
| Product category | Recreational crafts |
| Туре | Consumer |
| Product | Recreational craft |
| Name | SUN ODYSSEY 440 |
| Packaging description | No packaging. |
| Brand | SPBI-JEANNEAU |
| Product description | Recreational craft. Product sold online. |
| Risk type | Drowning |
| Risk description | Due to a gluing problem, the bow thruster flange may detach and generate a waterway. The boat may sink, increasing the risk of drowning for users. |
| Legal provisions (at EU level) and European standards against which the product was tested and did not comply | The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive. |
| Country of origin | France |
| | |

14/06/2024

Page 1

| Measures taken by | Recall of the product from end users |
|--------------------------|--------------------------------------|
| economic operators | Manufacturer |
| Date of entry into force | 16/05/2024 |



| Notifying country | France |
|---|--|
| Product category | Recreational crafts |
| Туре | Consumer |
| Product | Recreational craft |
| Name | SUN ODYSSEY 490 |
| Brand | SPBI-JEANNEAU |
| Type / number of model | SUN ODYSSEY 490 |
| Product description | Recreational craft. Product sold online. |
| Risk type | Drowning |
| Risk description | Due to a gluing problem, the bow thruster flange may detach and generate a waterway. The boat may sink, increasing the risk of drowning for users. |
| Legal provisions (at EU level) and European standards against which the product was tested and did not comply | The product does not comply with the requirements of the Recreational Craft and Personal Watercraft Directive. |
| Country of origin | France |
| 21/06/2024 | Page 1 |

| Measures taken by | Recall of the product from end users |
|--------------------------|--------------------------------------|
| economic operators | Manufacturer |
| Date of entry into force | 16/05/2024 |