

Marine Notice No. 37 of 2012

Notice to all Shipowners, Fishing Vessel Owners, Agents, Shipmasters, Skippers, Fishermen, Yachtsmen and Seafarers

Recall of Mullion "Compact 150N ISO 12402" - Lifejacket

The Department of Transport, Tourism and Sport has been advised that Mullion (manufacturer of Lifejacket COMPACT 150N ISO 12402) is recalling certain lifejackets as a precaution for inspection and, where appropriate, repair or replacement.

The purpose of this Marine Notice is to draw attention to the attached Mullion Technical Safety Alert.

Owners of the lifejackets in question can get further information on the recall process at the Mullion helplines below:

Ireland

087 9953192

between 09.00 and 17.00

UK

0044 (797) 11 03 798

between 09.00 and 17.00

International calls outside Ireland/UK 0032 (51) 74 15 21 between 09.00 and 17.00.

Director General, Maritime Safety Directorate, Department of Transport, Tourism and Sport, Leeson Lane, Dublin 2, Ireland.

26/07/2012

Encl. Annex

For any technical assistance in relation to this Marine Notice, please contact:
The Marine Survey Office, Leeson Lane, Dublin 2, tel: +353-(0)1-678 3400.
For general enquiries, please contact the Maritime Safety Policy Division, tel: +353-(0)1-678 3418.
Written enquiries concerning Marine Notices should be addressed to:
Maritime Safety Directorate, Department of Transport, Tourism and Sport, Leeson Lane, Dublin 2, Ireland.
email: marinenotices@dttas.ie or visit us at: www.dttas.ie




MULLION TECHNICAL SAFETY ALERT


COMPACT 150N ISO 12402-LIFEJACKET

It has come to our attention that a problem may occur during the inflation of the above mentioned lifejacket.

In order to avoid any potential safety issue, Mullion is recalling COMPACT-lifejackets which have been sold since 1st December 2011 if they have a yellow valve in the oral tube (see picture on the left below).

COMPACT lifejackets having a red valve in the oral tube are not affected and are not subject to this recall (see picture on the right below).





This problem arose after a design change on the oral tube initiated by our supplier. Although this new design oral tube is a fully approved and certified product, we have noticed there may be a malfunction of the lifejacket upon inflation.

The affected lifejackets are being recalled as a precaution for inspection and, where appropriate, repair or replacement.

Owners of lifejackets as described above should:

NOT USE THEM.

RETURN them to the nearest Mullion Lifejacket Service Station or the Mullion factory in Ireland as per the listings and details on our website at www.mullion-pfd.com under the heading **COMPACT LIFEJACKET**RECALL or click on the following link: http://www.mullion-pfd.com/compact-life-jacket-recall-programme

Owners of these lifejackets seeking further information on the recall process can call the Mullion Helplines as below:

UK +44 (797) 11 03 798 / Ireland + 353 87 9953192 between 09.00 and 17.00 -- International calls outside of the UK/Ireland +32 (51) 74 15 21 between 09.00 and 17.00

Owners can also make contact by email mullion@sioen.com